

Note: Be sure to properly remove old glue and fletching from arrow to be re-fletched before using *Max Clean Wipes*.



**WARNING:**  
CANCER AND REPRODUCTIVE HARM  
[www.P65Warning.ca.gov](http://www.P65Warning.ca.gov)

**ARIZONA ARCHERY ENTERPRISES, INC.**  
2781 N. Valley View Drive • Prescott Valley, AZ 86314  
[www.arizonaarchery.com](http://www.arizonaarchery.com)



# ARROW WIPES MAX CLEAN



# MAX CLEAN ARROW WIPES

10 PACK

AAE's *Max Clean Arrow Wipes* are a quick, easy, and clean method of cleaning arrow shafts for proper fletching adhesion. No more spilling liquids or smelly chemicals in you house or shop when prepping arrow for new shaft or re-fletching projects! *Max Clean Wipes* can be used on all forms of Carbon, Aluminum and Crested arrows.

#### Instructions:

1. Remove 1 *Max Clean Arrow Wipe* from the package. Vigorously wipe the end of the arrows to be fletched. 1 wipe per dozen arrow is recommended.
2. Do not touch wiped area after wiping due to oil residue on fingers.
3. Allow wiped arrow to dry for 60 seconds.
4. Once the arrows have dried, begin fletching.
5. When using a cyanoacrylate fast setting glue, hold in jig for 10 seconds then allow glue to properly set for 1 minute.